

Washington State Department of Ecology Hazardous Waste and Toxics Reduction Program

RCRA Site ID: WAH000050091	Facility Name: Treoil Industries	Date: 5/27 and 5/14, 2015
Generator Status:	Facility Address: 4242 Aldergrove Road, Ferndale	

Area & Description	Photographs
--------------------	-------------

(email 5/27, Mindy Collins to Jagroop S Gill)

“Atul described the contents of this as tall oil in various fractions (heavier, thicker part at bottom, lighter near top). He and I agreed that the contents of this tote would be similar to other tall oil around the site (color and odor same as other tall oil I’ve been shown many times). Atul felt that this tall oil may have come from skimming the surface of the containment area, but he was not certain.”

We sampled the entire profile of this container.”



(email 5/27, from Mindy Collins to Jagroop Gill)


“Hi Jay,

“While sampling today we discovered two open drums of something with white crystals forming along the walls of the drums. I checked the pH of the liquid, and it was over 13. I wrote “caution” on the drums. I just wanted to alert you to this. I don’t want anyone to touch the liquid or trip over it and injure themselves.”

Mindy”

Washington State Department of Ecology Hazardous Waste and Toxics Reduction Program

RCRA Site ID: WAH000050091	Facility Name: Treoil Industries	Date: 5/27 and 5/14, 2015
Generator Status:	Facility Address: 4242 Aldergrove Road, Ferndale	



The totes shown below were moved under cover as of May 14, 2015.

